



Combined Lamp Support and Terminal Box
and Wire Outlet for Position Light Signals

Combined Lamp Support and Terminal Box and Wire Outlet for Position Light Signals

(Continued)

Order by Plate, Piece, Reference and Abbreviated
Description Given in Heavy Face Type Only

Piece	Ref.	Description	Drawing Reference
	17	Machine Screw, $\frac{5}{16}$"-18x$\frac{3}{4}$" Fil. Hd. S. for fastening Refs. 6, 7, 8 and 9 to Ref. 2.	
70369	17a	Washer for Ref. 13	7826-180
95838	18	U-Bolt, $\frac{3}{4}$" with $\frac{3}{4}$" Hex. Nut and $\frac{3}{4}$" Lock Washer ($\frac{3}{16}$"x$\frac{3}{16}$" for Ref. A	8782-159
97611	19	Wire Outlet with Gasket for Ref. A for 5" or 6" Pipe (without U-Bolt)	B-10342-41
97619	19a	Gasket for Ref. 19	8078-942
	20	Conduit, 2" I. D. x$2\frac{9}{16}$" O. D. Greenfield double strip flexible. (Specify length when ordering).	
46567	21	U-Bolt, $\frac{1}{2}$" with $\frac{1}{2}$" Hex. Nut and $\frac{1}{2}$" Lock Washer ($\frac{3}{16}$"x$\frac{3}{32}$" for 5" Pipe for Ref. 19	8782-77
60389	21a	U-Bolt, $\frac{1}{2}$" with $\frac{1}{2}$" Hex. Nut and $\frac{1}{2}$" Lock Washer ($\frac{3}{16}$"x$\frac{3}{32}$" for 6" Pipe for Ref. 19	8782-109